



Ontario Inspection Report under the Aggregate Resource Act

Site Description

| | | | |
|----------------------------------|---------------------------------------|-------------------------------|------------------|
| Date of Inspection: | July-23-15 | Licence/Permit Number: | 5500 |
| Licensee/Permittee Name: | HANSON BRICK LTD./BRIQUES HANSON LTEE | | |
| Site Name: | Aldershot Quarry | | |
| Address: | 1570 Yorkton Court , Burlington | E-Mail Address: | |
| Lot(s): | Pt 2,3 & Pt 1,2,3 | Conc.(s): | 1 & 2 |
| Local Municipality: | BURLINGTON | Township: | EAST FLAMBOROUGH |
| County/Region: | HALTON R | Mining Claim #: | |
| Licence/Permit Area (ha): | 62.4 | UTM# (NAD 83): | |
| Inspection Category: | Initial | Extraction Area (ha): | 53.1 |
| Operation Type: | Quarry | Authority Type: | Class A Licence |
| Above Water: | Yes | Operating Status: | Operating |

Critical Inspection Items

Inspection Results: ✓ Compliance X Non Compliance n/a Not applicable n/i Not Inspected

A. General

1. ✓ Identification Sign 2. ✓ Gates 3. ✓ Entrance/Exit:

B. Operational

1. n/i Berms 2. n/i Setbacks 3. ✓ Stockpile Location
 4. ✓ Face Heights 5. ✓ Trees within 5m 6. n/i Extraction Depth
 7. ✓ Buildings 8. n/i Stripping 9. n/i Progressive Rehab
 10. n/i Inert Fill 11. ✓ Undercutting 12. n/i GPS Corners
 13. n/i Boundary Demarcation

C. Equipment

1. n/a Asphalt Plant 2. n/a Concrete Plant 3. n/a Portable Crusher
 4. n/i Permanent Crusher 5. n/i Wash Plant 6. n/i Screening Plant

D. Environmental

1. n/i Pumping 2. n/i Discharging (ECA) 3. n/i Ditching
 4. n/i Permit to take Water 5. n/i ECA 3 6. X Scrap
 7. ✓ Dust 8. n/i Fuel Storage 9. n/i ESA
 10. n/i PSW 11. n/i Woodlands 12. n/i ANSI

E. Recycling

1. n/a Asphalt (RAP) 2. n/a Concrete 3. n/a Glass
 4. ✓ Bricks 5. n/a Slag 6. n/a Asphalt Shingles

F. Monitoring Reports

1. n/i Water Monitoring 2. n/i Noise Monitoring 3. n/a Blast Monitoring
 4. n/i AMP

G. Other / Notes

